

**SURVEY PROCEDURES MANUAL
FOR THE
ENVIRONMENTAL SURVEY AND SITE ASSESSMENT PROGRAM**

Oak Ridge Institute for Science and Education
Oak Ridge Associated Universities
Oak Ridge, Tennessee 37831-0117

CONTROLLED MANUAL _____ UNCONTROLLED MANUAL _____

MANUAL NUMBER _____

ISSUE DATE _____

ISSUED TO _____

**TABLE OF CONTENTS
AND
RECORD OF REVISIONS**

SECTION	REVISION	IMPLEMENTATION DATE
1.0 INTRODUCTION	10	12/09/97
2.0 ORGANIZATION AND RESPONSIBILITIES	12	11/07/03
3.0 SUMMARY OF ACTIVITIES		
3.1 Job Hazard Analysis - Survey Mobilization and Demobiliation	0	09/28/00
4.0 QUALITY ASSURANCE AND QUALITY CONTROL		
4.1 General Information	1	09/28/00
4.2 Training and Certification	3	11/07/03
4.3 Records and Reports	1	09/28/00
4.4 Equipment and Instrumentation	2	02/28/03
4.5 Sample Handling	2	02/28/03
4.6 Job Hazard Analysis - Sample Screening	0	02/28/03
5.0 INSTRUMENT CALIBRATION AND OPERATIONAL CHECK-OUT		
5.1 General Information	10	09/28/00
5.2 Electronic Calibration of Ratemeters	12	02/28/03
5.3 Gamma Scintillation Detector Check-Out and Cross Calibration	12	02/28/03
5.4 Alpha Scintillation Detector Calibration and Check-Out	12	02/28/03
5.5 GM Detector Calibration and Check-Out	12	02/28/03
5.6 Proportional Detector Calibration and Check-Out	12	02/28/03
5.7 Alpha/Beta Scintillation Detector Calibration and Check-Out	12	02/28/03
5.8 Pressurized Ionization Chamber Calibration and Check-Out	11	02/28/03

SECTION		REVISION	IMPLEMENTATION DATE
5.9	The Bicon Micro-Rem Meter Check-Out	12	02/28/03
5.10	Compensated GM Detector Calibration and Check-Out	12	02/28/03
5.11	Floor Monitor Check-Out	12	02/28/03
5.12	Ionization Survey Meter Calibration and Check-Out	11	09/28/00
5.13	Collimated Gamma Scintillation Detector Check-Out	11	09/28/00
5.14	Field Measuring Tape Calibration	11	09/28/00
5.15	Rotameter Calibration	12	02/28/03
5.16	Reserved - SR60 Setup and Operation	NA	NA
5.17	GM Detector-Based Pipe Monitor Calibration and Check-Out	0	11/07/03
5.18	Job Hazard Analysis - Instrument Calibration and Setup (Previously Section 5.17)	2	11/07/03
6.0	SITE PREPARATION		
6.1	Clearing to Provide Access	11	02/28/03
6.2	Reference Grid System	11	02/28/03
6.3	Job Hazard Analysis - Site Clearing and Gridding	0	09/28/00
7.0	SCANNING AND MEASUREMENT TECHNIQUES		
7.1	Surface Scanning	11	02/28/03
7.2	Gamma Logging of Boreholes	10	09/28/00
7.3	Alpha Radiation Measurement	12	02/28/03
7.4	Beta Radiation Measurement	12	02/28/03
7.5	Gamma Radiation (Exposure Rate) Measurement	12	02/28/03
7.6	Reserved - SR60 Field Operation		

SECTION		REVISION	IMPLEMENTATION DATE
7.7	Beta Measurements Using the GM- Based Pipe Monitor	0	11/07/03
7.8	Job Hazard Analysis - Surface Scanning and Surface Activity Measurements	2	09/02/04
8.0	SAMPLING PROCEDURES		
8.1	Surface Soil Sampling	12	02/28/03
8.2	Subsurface Soil Sampling	11	09/28/00
8.3	Sediment Sampling	11	09/28/00
8.4	Water Sampling	13	11/07/03
8.5	Vegetation Sampling	11	09/28/00
8.6	Air Sampling	11	09/28/00
8.7	Determination of Removable Activity	12	02/28/03
8.8	Miscellaneous Sampling	11	09/28/00
8.9	Surface Soil Sampling for Chemical Analysis	2	02/28/03
8.10	Subsurface Soil Sampling for Chemical Analysis	2	02/28/03
8.11	Surface Water and Ground Water Sampling for Chemical Analysis	1	09/28/00
8.12	Swab Surface Sampling for Chemical Analysis	1	09/28/00
8.13	Sampling Equipment Preparation for Chemical Sampling	2	02/28/03
8.14	Field Decontamination of Chemical Sampling Equipment	1	09/28/00
8.15	Sample Identification and Labeling	2	11/07/03
8.16	Sample Chain-of-Custody	2	02/28/03
8.17	Job Hazard Analysis - Sampling	1	02/28/03
9.0	INTEGRATED SURVEY PROCEDURES		
9.1	Background Measurements and Sampling	12	02/28/03
9.2	General Survey Approaches and Strategies	10	09/28/00

SECTION	REVISION	IMPLEMENTATION DATE
10.0 SAFETY AND CONTAMINATION CONTROL	12	02/28/03
1.0 Purpose		
2.0 Responsibilities		
3.0 Training		
4.0 Medical Surveillance		
5.0 Site Safety Assessments and Plans		
6.0 Communications		
7.0 Site Controls		
8.0 Area Monitoring		
9.0 Personal Protective Equipment		
10.0 Radiation and Contamination Control		
11.0 Handling of Hazardous Materials		
12.0 Radioactive/Hazardous Waste Handling and Disposal		
13.0 Standard Safe Work Practices		
14.0 Excessive Noise		
15.0 Heat Stress		
16.0 Confined Space Entry		
17.0 Heavy Equipment Operation		
18.0 Asbestos		
19.0 Work at Heights		
20.0 Electrical Hazards		
21.0 Compressed Gas Cylinders		
22.0 Excavation Entry		
23.0 Vehicle Operation		
24.0 Emergency Response		
APPENDIX A Radiological Guidelines	10	09/28/00
APPENDIX B Field Survey Forms	13	11/07/03

All procedures have been reviewed and approved by:

Program Director: Eric W. Abelquist (Original Signature on File) Date: 9/2/2004

Survey Projects Manager: Timothy J. Vitkus (Original Signature on File) Date: 9/2/2004

Quality Manager: Ann T. Payne (Original Signature on File) Date: 9/2/2004