

ASTM DECOMMISSIONING STANDARD GUIDES

E 1034 Specification for Nuclear Facility Transient Worker Records

E 1167 Guide for Radiation Protection Program for Decommissioning Operations

E 1168 Guide for Radiological Protection Training for Nuclear Facility Workers

E 1278 Guide for Radioactive Pathway Methodology for Release of Sites Following Decommissioning

E 1281 Guide for Nuclear Facility Decommissioning Plans

E 1760 Guide for Unrestricted Disposition of Bulk Materials Containing Residual Amounts of Radioactivity

E 1819 Guide for Environmental Monitoring Plans for Decommissioning of Nuclear Facilities

E 1892 Guide for Preparing Characterization Plans for Decommissioning Nuclear Facilities

E 1893 Guide for Selection and Use of Portable Radiological Survey Instruments for Performing In Situ Radiological Assessments in Support of Decommissioning

E 2216 Guide for Evaluating Disposal Options for Concrete from Nuclear Facility Decommissioning

E 2420 Guide for Post-Deactivation Surveillance and Maintenance of Radiologically Contaminated Facilities

E 2421 Guide for Preparing Waste Management Plans for Decommissioning Nuclear Facilities

These guides are published in the 2005 ASTM Annual Book of Standards, Nuclear, Solar and Geothermal Energy, Volume 12.02

November 2005 data