

**TABLE OF CONTENTS
AND
RECORD OF REVISIONS**

	REVISION	DATE
Organization and Responsibilities	12	November 7, 2003
Abbreviations and Acronyms	0	May 1, 2001
Quality Control Procedures		
QCP1 Training and Certification	10	May 1, 2001
QCP2 Balance Quality Control	11	May 1, 2001
QCP3 Preparation, Control, and Traceability of Standards	12	August 31, 2004
QCP4 Control of Laboratory Logbooks	11	May 1, 2001
QCP5 Analytical Quality Control and Sample Flow	11	February 28, 2003
QCP6 Radiochemical Contamination Control	10	May 1, 2001
QCP7 Automatic Pipet Quality Control	10	May 1, 2001
QCP8 Counting Room Quality Control	0	May 1, 2001
QCP9 pH Meter Quality Control	0	January 7, 2004
Instrument Procedures		
IP1 Electronic Calibration of Bicon Analyst Ratemeters	0	May 1, 2001
IP2 Alpha Scintillation Detector Calibration and Check-Out	0	May 1, 2001
IP3 GM Detector Calibration and Check-Out	0	May 1, 2001
Sample Preparation		
SP1 Sample Receipt	0	May 1, 2001
SP2 Sample Log-In	0	May 1, 2001
SP3 Sample Preparation	3	August 31, 2004
Analytical Procedures		
AP1 Gross Alpha and Beta for Various Matrices	14	November 7, 2003

**TABLE OF CONTENTS
AND
RECORD OF REVISIONS (Continued)**

REVISION

DATE

Analytical Procedures (Continued)

	AP2	Determination of Tritium	14	November 7, 2003
	AP3	Isotopic Determination of Americium, Plutonium, Uranium, Neptunium, and/or Thorium in Soil, Water, Air Filters, and Biotic Material	16	January 25, 2002
	AP4	Determination of Total Radiostrontium in Environmental Samples	12	November 7, 2003
	AP5	Determination of Technetium-99	15	November 7, 2003
	AP6	Determination of Carbon-14 and Tritium Using the Biological Material Oxidizer	14	November 7, 2003
	AP7	Radium-226 in Water and Soil Using Alpha Spectroscopy	15	June 30, 2004
Non-Routine	AP8	Radium-228 in Water	2	November 7, 2003
Non-Routine	AP9	Analysis of Carbon-14 in Water and Smears	2	November 7, 2003
Non-Routine	AP10	Analysis of Plutonium-241 in Environmental Samples by Liquid Scintillation Analysis	2	November 7, 2003
	AP11	Sequential Determination of the Actinides in Environmental Samples Using total Sample Dissolution and Extraction Chromatography	2	November 7, 2003
Non-Routine	AP12	Determination of Nickel-63 in Environmental Samples	3	November 7, 2003
Non-Routine	AP13	Determination of Iron-55 in Water	3	November 7, 2003
Non-Routine	AP14	Determination of Sulfur-35 in Solid Environmental Samples	5	November 7, 2003

Counting Procedures

	CP1	Gamma Spectroscopy	14	August 31, 2004
	CP2	Alpha Spectroscopy	12	March 16, 2004
	CP3	Low Background Alpha/Beta Counter	2	November 7, 2003
	CP4	Liquid Scintillation Analyzer (LSA)	3	November 7, 2003

**TABLE OF CONTENTS
AND
RECORD OF REVISIONS (Continued)**

	REVISION	DATE
Waste Procedure		
WP1 Waste Generation Procedure	0	May 1, 2001
Appendix		
Job Hazard Analyses	1	December 16, 2003

All procedures have been reviewed and approved by:

Program Director: Eric W. Abelquist (Original Signature on File) Date: 8/31/2004

Laboratory Manager: Dale Condra (Original Signature on File) Date: 8/31/2004

Quality Manager: Ann T. Payne (Original Signature on File) Date: 8/31/2004